



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901425464																				
11/29/2019 7:14 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	0.02	2930773.98154352 1805696.32196773	Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901088483																				
3/19/2019 2:38 PM	Clear	Dry	0	0	0	0	Sideswipe Same Direction	Daylight	0.96	2930745.72712262 1805993.12663098	SUV	North	Passing/Ov ertaking	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Van/Mini- Van	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901070823																				
2/28/2019 4:34 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.98	2930751.8161343 1805871.68355252	Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901184617																				
6/11/2019 2:55 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.99	2930753.29687946 1805842.1506619	Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901262861																				
8/2/2019 6:20 PM	Clear	Dry	0	0	0	0	Turning	Daylight	0.99	2930753.26138608 1805842.85854194	Passenger	North	Turning Right	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
											Passenger	North	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901418811																				
11/23/2019 10:38 AM	Cloudy/Overcast	Dry	1	1	3	0	Turning	Daylight	0.99	2930753.25259763 1805843.03382438	Passenger	Northeast	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	West	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901451430																				
12/12/2019 2:04 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.99	2930752.16042405 1805864.81682117	Van/Mini-Van	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901020554																				
1/12/2019 1:57 PM	Snow	Snow or Slush	0	0	0	0	Front to Rear	Daylight	160.03	2930556.22737273 1805786.44552949	Passenger	East	Slow/Stop - Left Turn	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901140488																				
5/10/2019 3:20 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	160.05	2930661.63447006 1805802.70140648	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901025618																				
1/15/2019 12:13 PM	Clear	Dry	0	0	1	0	Sideswipe Same Direction	Daylight	160.07	2930775.18286063 1805799.54375277	SUV	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901065720																				
2/23/2019 4:35 PM	Rain	Wet	0	1	0	0	Turning	Daylight	160.07	2930755.55401752 1805796.75955558	Passenger	East	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901140256																				
5/9/2019 5:55 PM	Cloudy/Overcast	Dry	0	0	2	0	Turning	Daylight	160.07	2930771.0425032 1805805.64255251	Passenger	Southwest	Turning Left	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Straight Ahead	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2
201901146883																				
5/16/2019 7:15 AM	Clear	Dry	0	0	1	0	Angle	Daylight	160.07	2930771.0425032 1805805.64255251	Passenger	South	Straight Ahead	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Straight Ahead	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2
201901173812																				
6/5/2019 4:38 PM	Clear	Dry	0	0	1	0	Front to Rear	Daylight	160.07	2930755.57283301 1805796.76052918	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	2
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901189498																				
6/13/2019 12:34 PM	Clear	Dry	0	0	2	0	Front to Rear	Daylight	160.07	2930771.0425032 1805805.64255251	Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
											Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	2
											SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3

201901212699																				
6/25/2019 2:28 PM	Clear	Dry	2	0	0	0	Turning	Daylight	160.07	2930771.0425032 1805805.64255251										
											SUV	South	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2

201901225506																				
7/10/2019 5:23 AM	Clear	Dry	0	0	0	0	Fixed Object	Daylight	160.07	2930771.0425032 1805805.64255251										
											SUV	South	Skidding/Co ntrol Loss	Ran Off Roadway	Off Pavement - Right	Light Support	Off Pavement - Right	(UNK)	(UNK)	1

201901261182																				
7/28/2019 12:46 PM	Clear	Dry	0	0	0	0	Turning	Daylight	160.07	2930771.0425032 1805805.64255251										
											SUV	North	Turning Right	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	1
											Van/Mini- Van	North	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2

201901259627																				
7/31/2019 6:16 PM	Clear	Dry	0	0	0	0	Turning	Daylight	160.07	2930771.0425032 1805805.64255251										
											Passenger	South	Turning Right	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	South	Turning Right	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2

201901260474																				
8/2/2019 12:50 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	160.07	2930771.0425032 1805805.64255251										
											Pickup	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901260351																				
8/4/2019 12:25 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	160.07	2930771.0425032 1805805.64255251	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	2
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901289144																				
8/21/2019 9:19 AM	Clear	Dry	0	0	1	0	Turning	Daylight	160.07	2930771.0425032 1805805.64255251	Passenger	Southwest	Turning Left	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	1
											Van/Mini-Van	East	Straight Ahead	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2
201901299348																				
8/26/2019 5:11 PM	Clear	Dry	0	0	0	0	Rear to Front	Daylight	160.07	2930771.0425032 1805805.64255251	SUV	East	Backing	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901299344																				
8/27/2019 9:53 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	160.07	2930771.0425032 1805805.64255251	SUV	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901321011																				
9/12/2019 9:47 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	160.07	2930771.0425032 1805805.64255251	Passenger	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901341276																				
9/24/2019 2:50 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	160.07	2930755.57283301 1805796.76052918	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901391457																				
10/30/2019 11:57 AM	Rain	Wet	0	0	3	0	Turning	Daylight	160.07	2930755.4465738 1805796.75399598	SUV	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	South	Turning Right	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901385082																				
10/30/2019 2:48 PM	Rain	Wet	0	0	0	0	Turning	Daylight	160.07	2930754.75959388 1805796.71844865	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Van/Mini-Van	South	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901195151																				
6/15/2019 11:52 AM	Rain	Wet	0	0	1	0	Front to Rear	Daylight	160.09	2930880.45054005 1805808.58420659	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901157859																				
5/23/2019 12:19 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	160.10	2930907.80254984 1805809.3196995	SUV	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901026255																				
1/18/2019 2:14 PM	Clear	Dry	0	0	1	0	Front to Rear	Daylight	160.11	2930959.60865213 1805823.28399059	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901172179																				
6/4/2019 3:13 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	3.25	2930775.52124493 1805799.59177917	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901344050																				
9/29/2019 6:47 PM	Rain	Wet	0	0	0	0	Turning	Darkness, Lighted Road	3.25	2930771.0425032 1805805.64255251	Passenger	North	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	Southeast	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901367671																				
10/15/2019 10:30 AM	Cloudy/Overcast	Dry	0	0	0	0	Turning	Daylight	3.25	2930771.0425032 1805805.64255251	SUV	Southeast	Turning On Red	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	Southwest	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901424096																				
11/27/2019 6:27 PM	Clear	Dry	0	0	0	0	Turning	Darkness, Lighted Road	3.25	2930771.0425032 1805805.64255251	Passenger	South	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901430269																				
12/1/2019 1:50 PM	Rain	Wet	0	0	0	0	Front to Rear	Daylight	3.25	2930771.0425032 1805805.64255251	SUV	East	Skidding/Control Loss	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2
201901438069																				
12/9/2019 2:07 PM	Clear	Wet	0	0	0	0	Front to Rear	Daylight	3.25	2930771.0425032 1805805.64255251	Passenger	East	Skidding/Control Loss	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901453179																				
12/21/2019 11:48 AM	Clear	Dry	0	2	0	0	Turning	Daylight	3.25	2930771.0425032 1805805.64255251	Passenger	Southwest	Turning Left	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Straight Ahead	Motor Vehicle In Traffic	Intersection	(UNK)	(UNK)	(UNK)	(UNK)	2
201901455829																				
12/23/2019 4:31 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	3.25	2930771.0425032 1805805.64255251	Passenger	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901089152																				
3/17/2019 2:03 PM	Clear	Dry	0	0	2	0	Front to Rear	Daylight	3.26	2930785.36480155 1805800.9888613	Pickup	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	2
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901229807																				
7/10/2019 5:26 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	3.26	2930807.90239975 1805804.18759086	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901123584																				
4/25/2019 11:11 AM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	3.27	2930854.55790151 1805810.80934049	Passenger	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901320990																				
9/10/2019 7:55 PM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	3.29	2930962.82535507 1805826.17558763	SUV	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											Unknown	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
<u>43</u>	<u>0</u>	<u>2</u>	<u>2</u>	<u>10</u>	<u>29</u>	<u>0</u>	<u>25</u>	<u>3</u>	<u>4</u>	<u>18</u>

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	1	2.3%	Monday	3	7.0%	05 AM	1	2.3%	Passenger	52	55.9%
Fixed Object	1	2.3%	Tuesday	9	20.9%	07 AM	1	2.3%	Pickup	3	3.2%
Front to Rear	24	55.8%	Wednesday	8	18.6%	09 AM	1	2.3%	SUV	32	34.4%
Rear to Front	1	2.3%	Thursday	8	18.6%	10 AM	2	4.7%	Unknown	1	1.1%
Sideswipe Same Direction	2	4.7%	Friday	5	11.6%	11 AM	4	9.3%	Van/Mini-Van	5	5.4%
Turning	14	32.6%	Saturday	5	11.6%	Noon	6	14.0%	TOTAL:	93	
TOTAL:	43		Sunday	5	11.6%	1 PM	2	4.7%			
			TOTAL:	43		2 PM	9	20.9%			
					3 PM	2	4.7%				
					4 PM	4	9.3%				
					5 PM	3	7.0%				
					6 PM	4	9.3%				
					7 PM	2	4.7%				
					9 PM	2	4.7%				
					TOTAL:	43					

<i>Weather Cond</i>	<i>Total</i>	<i>%</i>	<i>Light Cond</i>	<i>Total</i>	<i>%</i>	<i>Road Surface</i>	<i>Total</i>	<i>%</i>	<i>DIRP</i>	<i>Total</i>	<i>%</i>
Clear	33	76.7%	Darkness, Lighted Road	6	14.0%	Dry	35	81.4%	East	45	48.4%
Cloudy/Overcast	3	7.0%				Snow or Slush	1	2.3%	North	9	9.7%



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

<i>Weather Cond</i>	<i>Total</i>	<i>%</i>	<i>Light Cond</i>	<i>Total</i>	<i>%</i>	<i>Road Surface</i>	<i>Total</i>	<i>%</i>	<i>DIRP</i>	<i>Total</i>	<i>%</i>
Rain	6	14.0%	Daylight	37	86.0%	Wet	7	16.3%	Northeast	1	1.1%
Snow	1	2.3%	TOTAL:	43		TOTAL:	43		South	22	23.7%
TOTAL:	43								Southeast	2	2.2%
									Southwest	4	4.3%
									West	10	10.8%
									TOTAL:	93	



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2930757.487 : YCoordinate 1805796.079 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.