



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945430.519 : YCoordinate 1806498.71 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901113618																				
4/15/2019 11:46 AM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	0.00	2945447.07583673 1806642.38848731	SUV	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	2
											SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901315258																				
9/8/2019 2:25 PM	Cloudy/Overcast	Wet	0	0	0	0	Front to Rear	Daylight	0.00	2945447.6486538 1806522.06003076	SUV	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901414683																				
11/19/2019 8:00 PM	Clear	Wet	0	0	1	0	Angle	Darkness, Lighted Road	0.00	2945447.6486538 1806522.06003076	SUV	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901116268																				
4/16/2019 4:35 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	162.86	2945368.37588424 1806495.4089406	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901099305																				
3/14/2019 9:00 AM	Unknown	Unknown	0	0	0	0	Front to Rear	Daylight	162.87	2945427.74759624 1806551.56344088	Passenger	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945430.519 : YCoordinate 1806498.71 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
											Pickup	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901137043																				
5/4/2019 2:57 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	162.87	2945458.89008975 1806511.42888391	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901200155																				
6/19/2019 9:11 PM	Rain	Wet	0	1	0	0	Pedestrian	Darkness, Lighted Road	162.87	2945458.89008975 1806511.42888391	Passenger	East	Changing Lanes	Pedestrian	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901218505																				
6/30/2019 6:22 PM	Cloudy/Overcast	Dry	0	0	0	0	Front to Rear	Daylight	162.87	2945458.89008975 1806511.42888391	Passenger	East	Unknown	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Van/Mini-Van	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	2
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901220834																				
7/5/2019 9:04 AM	Clear	Dry	0	0	0	0	Sideswipe Same Direction	Daylight	162.87	2945458.89008975 1806511.42888391	SUV	East	Changing Lanes	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901372786																				
10/20/2019 5:28 PM	Clear	Dry	0	0	2	0	Front to Rear	Daylight	162.87	2945491.85138705 1806554.8018494	SUV	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Backing	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945430.519 : YCoordinate 1806498.71 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901089158																				
3/20/2019 9:41 PM	Rain	Wet	0	0	0	0	Front to Rear	Darkness, Lighted Road	162.88	2945492.21152685 1806555.06912789	Passenger	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901162547																				
5/26/2019 5:45 PM	Clear	Dry	0	1	1	0	Front to Rear	Daylight	162.88	2945492.01778011 1806554.74109341	SUV	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901267773																				
8/7/2019 11:34 AM	Clear	Dry	0	0	0	0	Turning	Daylight	162.88	2945490.788688 1806555.90258005	SUV	Southwest	Turning Right	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	Southwest	Turning Right	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901315389																				
9/5/2019 4:36 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	162.88	2945491.67557932 1806554.81016043	Passenger	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Straight Ahead	Motor Vehicle In Traffic	Intersectio n	(UNK)	(UNK)	(UNK)	(UNK)	2
201901421031																				
11/26/2019 6:49 AM	Clear	Dry	0	0	0	0	Turning	Daylight	162.88	2945492.36096257 1806554.53743316	SUV	West	Turning Right	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	West	Turning Right	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945430.519 : YCoordinate 1806498.71 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901386723																				
10/31/2019 5:09 PM	Snow	Wet	0	0	1	0	Front to Rear	Daylight	162.90	2945595.2718533 1806560.96191774	Passenger	West	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Pickup	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											SUV	West	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3
201901084884																				
3/14/2019 3:05 PM	Clear	Dry	0	0	1	0	Front to Rear	Daylight	39.01	2945427.72460329 1806551.99605286	Van/Mini-Van	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	South	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901399810																				
11/8/2019 8:51 PM	Clear	Dry	0	0	1	0	Angle	Darkness, Lighted Road	39.07	2945441.83791578 1806285.46497391	SUV	North	Straight Ahead	Motor Vehicle In Traffic	Other	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Straight Ahead	Motor Vehicle In Traffic	Other	(UNK)	(UNK)	(UNK)	(UNK)	2
201901079254																				
3/10/2019 2:07 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	6.04	2945405.73710966 1806497.13681014	Van/Mini-Van	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901085113																				
3/15/2019 7:43 PM	Clear	Wet	0	0	0	0	Front to Rear	Darkness, Lighted Road	6.04	2945380.84306054 1806495.98551843	SUV	East	Backing	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945430.519 : YCoordinate 1806498.71 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Date	Weather	Roadway	----- A	Injuries B	----- C	Killed	Type of Crash	Light Condition	Mile	XCoordinate YCoordinate	Vehicle Type	DIRP	Maneuver	Event 1	Loc 1	Event 2	Loc 2	Event 3	Loc 3	Unit
201901281725																				
8/18/2019 5:36 PM	Clear	Dry	0	0	0	0	Front to Rear	Daylight	6.04	2945394.76766336 1806496.62949883	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901411316																				
11/16/2019 4:22 AM	Clear	Dry	0	0	0	0	Front to Rear	Darkness, Lighted Road	6.05	2945458.89008975 1806511.42888391	Passenger	East	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901436846																				
12/8/2019 2:15 PM	Clear	Dry	0	0	0	0	Sideswipe Same Direction	Daylight	6.05	2945458.89008975 1806511.42888391	SUV	East	Changing Lanes	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	East	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901054551																				
2/13/2019 8:25 PM	Clear	Dry	0	0	0	0	Front to Front	Darkness, Lighted Road	6.66	2945501.29856918 1806372.67337051	Pickup	South	Backing	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											Passenger	North	Slow/Stop In Traffic	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
201901012367																				
1/3/2019 3:36 PM	Cloudy/Overcast	Dry	0	0	3	0	Turning	Daylight	6.70	2945425.13576036 1806600.70459054	SUV	South	Turning Left	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	1
											SUV	South	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	2
											SUV	North	Straight Ahead	Motor Vehicle In Traffic	On Pavement (Roadway)	(UNK)	(UNK)	(UNK)	(UNK)	3



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945430.519 : YCoordinate 1806498.71 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

TOTAL CRASHES	FATAL CRASHES	A INJURY CRASHES	B INJURY CRASHES	C INJURY CRASHES	PROPERTY DAMAGE CRASHES	TOTAL KILLED	TOTAL INJURED	A INJURIES	B INJURIES	C INJURIES
<u>25</u>	<u>0</u>	<u>0</u>	<u>2</u>	<u>6</u>	<u>17</u>	<u>0</u>	<u>12</u>	<u>0</u>	<u>2</u>	<u>10</u>

Type of Crash	Total	%	Day of Wk	Total	%	Hour of Day	Total	%	Vehicle Type	Total	%
Angle	2	8.0%	Monday	1	4.0%	04 AM	1	4.0%	Passenger	24	44.4%
Front to Front	1	4.0%	Tuesday	3	12.0%	06 AM	1	4.0%	Pickup	4	7.4%
Front to Rear	16	64.0%	Wednesday	4	16.0%	09 AM	2	8.0%	SUV	23	42.6%
Pedestrian	1	4.0%	Thursday	5	20.0%	11 AM	2	8.0%	Van/Mini-Van	3	5.6%
Sideswipe Same Direction	2	8.0%	Friday	3	12.0%	2 PM	4	16.0%	TOTAL:	54	
Turning	3	12.0%	Saturday	2	8.0%	3 PM	2	8.0%			
TOTAL:	25		Sunday	7	28.0%	4 PM	2	8.0%			
			TOTAL:	25		5 PM	4	16.0%			
					6 PM	1	4.0%				
					7 PM	1	4.0%				
					8 PM	3	12.0%				
					9 PM	2	8.0%				
					TOTAL:	25					

<i>Weather Cond</i>	<i>Total</i>	<i>%</i>	<i>Light Cond</i>	<i>Total</i>	<i>%</i>	<i>Road Surface</i>	<i>Total</i>	<i>%</i>	<i>DIRP</i>	<i>Total</i>	<i>%</i>
Clear	18	72.0%	Darkness, Lighted Road	7	28.0%	Dry	18	72.0%	East	22	40.7%
Cloudy/Overcast	3	12.0%	Daylight	18	72.0%	Unknown	1	4.0%	North	6	11.1%
Rain	2	8.0%	TOTAL:	25		Wet	6	24.0%	South	10	18.5%
Snow	1	4.0%				TOTAL:	25		Southwest	2	3.7%

**Coordinate Collision Diagram Report****1/1/2019 to 12/31/2019**

For XCoordinate 2945430.519 : YCoordinate 1806498.71 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

<i>Weather Cond</i>	<i>Total</i>	<i>%</i>
Unknown	1	4.0%
TOTAL:	25	

<i>DIRP</i>	<i>Total</i>	<i>%</i>
West	14	25.9%
TOTAL:	54	



Coordinate Collision Diagram Report

1/1/2019 to 12/31/2019

For XCoordinate 2945430.519 : YCoordinate 1806498.71 | Foot Tolerance : 250 | County : Cook | Intersection Related: All Cases | *See Notes at End of Report.

Notes

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in previous years since data prior to 2015 was physically located by bureau personnel.