

VILLAGE OF ORLAND PARK
PUBLIC WORKS DEPARTMENT
REQUEST FOR ACTION



Date Received: 3/18/09 Time Received: _____ AM / PM

Received by: J. Ingram Division: Storm Water P28002

REQUEST FROM: Name: _____ Address: 12630 Laketrail Drive

Home Phone: _____ Work Phone: _____ Cell Phone: Lake Lucille Pond

NATURE OF REQUEST: Outlet structure partially blocked with
Debris. Clear outlet structure remove all debris
from area. Also check adjacent inlet to insure it is not
see attached plans blocked.

ASSIGNED TO: _____ INSTRUCTIONS: Due to water level follow-up work may be required

ACTION TAKEN: Outlet structure was restricted with chicken wire and
rock. Removed obstructions and water level began to recede.
Removed debris from around outlet. 3-19-09 DS/OS/KS/KR
Moved rock from front of outlet structure to allow more flow.
Checked depth of inlet FES, 4 1/2' under water. No major obstructions
felt at FES.

Customer Signature: _____ Total Time: _____

FOLLOW-UP ACTION NEEDED: _____

MATERIALS USED: TK 23, TOOLS

DATE COMPLETED: 3-24-09 COMPLETED BY: DS/KS REVIEWED BY: _____

WORK ORDER NUMBER

N^o 62636

VILLAGE OF ORLAND PARK
PUBLIC WORKS DEPARTMENT
REQUEST FOR ACTION



Date Received: 6-27 Time Received: 12:55 AM / PM

Received by: _____ Division stormwater mgmt

P28-02

REQUEST FROM

Account Number: Kate Lucille

Name: Larry Harper Address: _____

Home Phone: 671-9707 Work Phone: _____

NATURE OF REQUEST

a lot of algae is in this pond right now the resident would like to know our quote for Orland Park. How much do we do for them? Please call and advise him.

ASSIGNED TO

APPOINTMENT SCHEDULED

INSTRUCTIONS

ACTION TAKEN

Weed and Algae control not performed outside VOP water problem is excessive and affects function of pond

Customer Signature: _____ Total Time: _____

FOLLOW UP ACTION NEEDED

MATERIALS USED

DATE COMPLETED

8/13/01


COMPLETED BY

REVIEWED BY

WORK ORDER NUMBER

29422

VILLAGE OF ORLAND PARK
PUBLIC SERVICES DEPARTMENT
REQUEST FOR ACTION



Date Received 3/26/97

Time Received _____

Received by JJI

Department _____

REQUEST FROM

Name 642 Lake Trail dr.

Address Lake Lucille Pond

Home Phone _____

Work Phone _____

Account Number _____

NATURE OF REQUEST

P28

Remove plywood blocking
outlet structure

Scheduled by _____

Date Scheduled _____

Assigned to _____

Instructions _____

Time out 10:30 Time in 10:45 Total Time 15 min

Material & Equipment TRK 58

ACTION TAKEN

REMOVED PLYWOOD FROM OUTLET
STRUCTURE

Follow up Action Required

Completed by D.V.

Supervisor _____


Date Completed 4-15-97

Date _____

WORK ORDER NUMBER

37127

VILLAGE OF ORLAND PARK
PUBLIC SERVICES DEPARTMENT
REQUEST FOR ACTION



Date Received 3-24-97

Time Received _____

Received by Levi

Department water

REQUEST FROM

NATURE OF REQUEST

P28

Name William Conway

Address 12603 S 104th St

Home Phone 361-5748

Work Phone _____

Account Number _____

selecting good behind house but
found that it was not turning into
manhole. He thinks he might be
being tampered with. Resident has
to be called after the problem is
checked into

Scheduled by _____

Date Scheduled _____

Assigned to _____

Instructions _____

ACTION TAKEN

CHECKED POND AND FOUND NOTHING
WRONG W/ INLETS OR OUTLETS. CHECKED
INLET BACKWARDS AND FOUND NO
SIGN OF TAMPERING OR BLOCKAGE.
LEFT MESSAGE ON RESIDENT'S MACHINE

Time out 1:30 Time in 2:00 Total Time 2HR

Material & Equipment TRK 58

Follow up Action Required

Completed by DV

Supervisor _____


Date Completed 3-24-97

Date _____

WORK ORDER NUMBER

37241

VILLAGE OF ORLAND PARK
PUBLIC SERVICES DEPARTMENT
REQUEST FOR ACTION



Date Received 5-28-97

Time Received 6:42

Received by Lu

Department water

REQUEST FROM

NATURE OF REQUEST

P28

Name Mrs. Thompson

like Lucille - expense account
last month sub found a leakage. But
now since then 2 hoses have been
built and the like is done again

Address 638 Lakeview Dr.

Home Phone 449-2570

Work Phone 650-574-4192

Account Number _____

Scheduled by _____

Date Scheduled _____

Assigned to _____

Instructions _____

Time out _____ Time in _____ Total Time _____

Material & Equipment _____

ACTION TAKEN

Checked outlet structure
water level approx 2" below
normal level - same as
last time it was checked.
left msg on machine

Follow up Action Required

Completed by J. Lopez

Supervisor _____


Date Completed 5/29/97

Date _____

WORK ORDER NUMBER

81626

VILLAGE OF ORLAND PARK
PUBLIC WORKS DEPARTMENT
REQUEST FOR ACTION



Date Received: 3-27-06 Time Received: 10:10 AM / PM

Received by: [Signature] Division: WPT P28-02

REQUEST FROM: Name: ALBERTA Address: 12541 104TH AVE

Home Phone: 671-1233 Work Phone: Lake Lucille

NATURE OF REQUEST: "LAKE LUCILLE" - DRAINING - 15' DIA

ASSIGNED TO: [Signature] INSTRUCTIONS:

ACTION TAKEN: Level material

Customer Signature: Total Time:

FOLLOW-UP ACTION NEEDED:


MATERIALS USED: TC 23

DATE COMPLETED: 3-28-06 COMPLETED BY: [Signature] REVIEWED BY: [Signature]

WORK ORDER NUMBER

NO 77917

VILLAGE OF ORLAND PARK
PUBLIC WORKS DEPARTMENT
REQUEST FOR ACTION



Date Received: 8-30-04 Time Received: 4:00 AM / PM PM

Received by: le Division: Water

REQUEST FROM: Name: Quintas Address: 620 Lake Trail Dr.

Home Phone: 557-0212 Work Phone: (Palms Park)

NATURE OF REQUEST: Lake Lucille needs to be looked at weeds, algae please advise.

ASSIGNED TO: _____ INSTRUCTIONS: _____

ACTION TAKEN: looked at pond - Every home around pond draws water for their sprinkler system. Significant submerged weeds exist around perimeter of ponds. Spoke to resident - told him I would NOT meet pond due to chance of killing grass if water is drawn from pond. Also informed resident that mosquito control is handled through SWCCMAD. Informed resident that current policy prohibits drawing water from pond for sprinkling purposes.

Customer Signature: _____ Total Time: _____

FOLLOW-UP ACTION NEEDED: _____

MATERIALS USED: _____

DATE COMPLETED: 9/3/04 COMPLETED BY: [Signature] REVIEWED BY: _____